


## Rotation of cutting head

1. This should be the power interference.



2. Take screws out on the DSP board which is in the electrical box

3. Add magnet ring.



4. Two positions need to be added with magnet ring.

Method of winding power cord.

1. Power cable in the electric box.



2. Computer cable and communication cable.

