

Requirements:

Width for the room: at least 8 m

Length for the room: the machine length is 5.3m, the length of the room depends on your spreading table.

Height for the room: at least 2.5m, if your room is much higher than 3.5m, you need to prepare a frame to hold the cables above the machine.

Weight of machine: 2850 Kg

Power Requirement: (50HZ、60HZ, Voltage±5%, PF=0.8)

Three-phase Vacuum Pump	Voltage	Electric Current	Wiring System
20KW	380V	50A	L1、L2、L3、G

Single-phase Machine and computer	Voltage	Electric Current	Wiring System
	220V	20A	L、N、G

Air Supply Requirements:


Air Pressure	0.8MPA
Air Flow	0.35m ³ /min

Tools will be used in installing GLS2520


Depth vernier caliper




Two sets of Allen wrench



Telescopic ruler (recommend)



Square ruler



tape measure



Red light level instrument

