


1. There are 3 wire need connection. Check the mark on the board and cable.

24vk is power supply wire connect to 24v

GND connect to GND

AND PRT (yellow wire) is the signal wire connect to INPUT



2. After finish connect the wire, then cover the board and EOT will looks like the follow picture

